

<b>SB Number:</b>	<b>SB 2G4-003</b>	<b>Creation Date:</b> 28/08/2007
<b>Subject:</b>	<b>Firmware upgrade, Ver. V1.68B/V.2.12F (system)</b>	
<b>Model:</b>	<b>FS-1016MFP/1116MFP</b>	

The system firmware is upgraded to correct the following phenomena:

#### FS-1016MFP

- The CCD image process timing has been changed to eliminate tiny white dots which may appear when copying in Photo or Mixed mode.

Type	Program No.	Check SUM	VER.
SYSTEM	3in1_V168B_Char.zip	-	V1.68B

=====

#### FS-1116MFP

- The CCD image process timing has been changed to eliminate tiny white dots which may appear when copying in Photo or Mixed mode.
- A total page defective display failure (at fax footer) has been corrected.
- The Fax board has been changed to comply with Argentinan telephone line standard.
- An on/off switch function for Ringer sound has been added.

Type	Program No.	Check SUM	VER.
SYSTEM	4in1_V212F_Char.zip	-	V2.12F

#### Serial number information:

All machines produced in August 2007 and onwards will have this firmware installed.