

Version List of Adjustment Program for Stylus COLOR 640

1999/8/26

Version	Corrected Points	Changed parts (Adaptive module)	T/I No. and Issued Date	Remark
1.0	First release		TE98-099 (JUL. 21, 1998)	
1.1a	1. Handshake timing for reverse channel is added 10msec. 2. Speed parameter for CR motor is changed to 80cps. 3. Corresponding to previous products. Actually corresponding to PROM's bug about lacking of Colon in Reply-data format. 4. Add DES(destination) for Device ID. 5. Destination for Korea is added.	1: Change module; nibble.cpp 2: Change module; Oangulr.cppl 3: Change module; dest.cpp, Oabsorp.cpp, Obid.cpp, Ohdvol.cpp, Opattern.cpp 4: Change module; database.cpp 5: Change module; database.cpp datawrit.cpp, dest.cpp, inkjet.h	TE98-180 (OCT. 8, 1998)	
1.1b	1. Handshake timing for reverse channel is added 10msec. 2. Speed parameter for CR motor is changed to 80cps. 3. Corresponding to recent products. Colon in Reply-data format was added and Reply-data format was corrected. 4. Add DES(destination) for Device ID. 5. Destination for Korea is added.	1: Change module; nibble.cpp 2: Change module; Oangulr.cppl 3: Revert module; dest.cpp, Oabsorp.cpp, Obid.cpp, Ohdvol.cpp, Opattern.cpp 4: Change module; database.cpp 5: Change module; database.cpp datawrit.cpp, dest.cpp, inkjet.h	TE98-180 (OCT. 8, 1998)	
1.2a	1. A function of reading the head ID is changed.	1: Change module; Ohdvol.cpp	TE98-242 (NOV. 5, 1998)	
1.2b	1. A function of reading the head ID is changed.	1: Change module; Ohdvol.cpp	TE98-242 (NOV. 5, 1998)	
3.0a	1. This version is corresponding to previous issued program ver.1.2a. 2. User interface is changed. 3. Recovery routine for clogged black nozzle is added.	2: Change module; almost all 3: Change module; fadjust.cpp Add module; finkstp.cpp	TE98-316 (JAN. 21, 1999)	

Version List of Adjustment Program for Stylus COLOR 600 / 640 / 660

1999/8/26

Version	Corrected Points	Changed parts (Adaptive module)	T/I No. and Issued Date	Remark
3.0	1. Previous issued program for Stylus COLOR 600 ver.1.5 is united to program for Stylus COLOR 640 ver.1.2b. 2. User interface is changed. 3. Recovery routine for clogged black nozzle is added.	2: Change module; almost all 3: Change module; fadjust.cpp Add module; finkstp.cpp	TE98-316 (JAN. 21, 1999)	
4.0	1. DOS program changed into Windows program. 2. Previous issued program for Stylus COLOR 600 and 640 ver.3.0 is united to program for Stylus COLOR 660.	1: Change module; almost all 2: Change module; almost all	TE99-136 (AUG. 26, 1999)	